


MAK 6M20

> M20 SPARES

S/N	ITEM	QTY
1	Reusable Cyl Heads Bare-Pressure Tested Free From Crack	8-10
2	Piston With Groove With in Limit	8-10
3	Con Rod-Free From Crack, Wear Within Limit	8-10
4	Fuel Pump-Good Condition	8-10
5	Reusable Liners Wear Below 0.20mm-Free From Crack, Welding or any Damages	8-10
6	L O Filter-Good Condition	2
7	Water Pump-Good Condition	1
8	Lube oil Pump-Good Condition	1
9	Turbo Charger K54-Good Condition	2
10	STD Condition 6M20 Crankshaft, Within Std Limits, no Crack, no Ovality, Hardness Within Limits	1
11	Cam Shaft 6M20-Good Condition	2
12	Woodward UG-8 - Good Condition	2
13	6M20 Engine Block-Good Condition	1
14	Cam Shaft Gear & Crankshaft Gear-Good Condition	2
15	FLY Wheel-Good Condition 6M20	1
16	After Cooler-Good Condition 6M20	1



EURO MARINE SERVICES

OFFICE:
307, MADHAV HILL, WAGHAWADI ROAD,
BHAVNAGAR, GUJARAT - INDIA 364 001.
PHONE : +91 -278-242,1754
e-mail: info@euroshipspares.com / euroshipspares@gmail.com
url: www.euroshipspares.com

Marine & Industrial Engines, Power Plants, Generators, Compressors, Separators, PHE, Turbo - All types of Equipments & Spare Parts Supplier



Thanks and Regards,
Mr.SANTOSH SHINDE
+91 9825205453

EURO MARINE SERVICES